

MALONE CENTRAL SCHOOL DISTRICT
TRANSPORTATION FACILITY DEFICIENCIES
UPDATED: 2013-2014

VENTILATION	Not an adequate system in the mechanic work bay No ventilation at all in the bus storage area
ROOF/CEILING	Leaks are present in various ceiling locations Showing rust and deterioration from the ceiling area Roof drains drain onto the garage floor in bus storage area
WALLS	Cracking and separating in several locations All man doors showing rust and deterioration. None are energy efficient
FLOORS	Cracking and deterioration exist in several places
DRAINAGE	During rainy season water will drain from drain pipe back into lift pits
ELECTRICAL	Electrical capacity needs to be updated and improved. Have extension cords running some pieces of equipment. No emergency backup generation exists
OFFICE AREA	Supervisor and assistant share an approximate 15' by 17' office Copy work is also conducted in this area No space exists to have meetings with drivers or driver/parent meetings Parts clerk office is shared with DOT and mechanics - 10' by 12' area No file storage area for records

Facility was built in the 60's when district had sixty passenger buses. Most buses are sixty-six passenger buses. There is not adequate room around the buses to perform proper pre and post trips per State Education Department regulations.

Rest rooms not adequate for staffing needs (i.e. too small for number of staff)

No area for training, district has to pull buses outside and use a bus bay for training meetings

Need to update O.S.H.A. compliant equipment (i.e. eye wash station, decontamination station)

No adequate area for drivers to work on paper work (i.e. D.V.I.R.'s, discipline referrals etc.)

No area for mechanics to clean up after performing their mechanic duties

No area to maintain buses for deterioration problems with body (i.e. rusting)

Parts storage inadequate

Garage doors are inefficient

Heating System is inefficient and unreliable (multiple times system has been inoperative)